Collective FA solutions

MITSUBISHI CNC C70 Safety Observation Function







Advantage: Provides extra safety for machine operations.

Benefit: Provides for more Automotive opportunities

European Safety Standard's **EN954-1 Category 3** is satisfied

<Basic function>

1. Safety signal comparison


- -Safety signals are input/output via two routes
- -Two CPUs compare the input/output signals

2. Speed monitoring

 -Two CPUs monitor if the commanded speed and actual speed exceed the safety speed or not (Servo/Spindle)

3. Redundant emergency stop

- External emergency stop signal is wired to the CNC CPU and Drive Unit
- -Drive Unit's main power is shut-down via two routes




Safety signal comparison function

- -Monitor whether the safety signals from/to the Sequence and CNC CPUs match or not
- -Both the Sequence and CNC CPUs execute the user safety sequence

-When a safety signal comparison error occurs, emergency stop will be carried

out to shut-down the Drive Unit power



Safety signal unit specification (Q173SXY)

- ◆20 input points and 12 output points for 2 systems
- ◆Up to 3 modules can be mounted

ł	۰	
0	0	l
O		l
		ľ

	Points	Signals	Remarks
Input	20	User safety signals	
Output	1	Shut-down signal	Turns ON when no signal comparison error is occurring
	1	Power shut-down signal	Turns ON when ready ON is possible
	10	User safety signals	


CNC side Sequence safety signal CPU safety signal


*The second and third units' output signals are all available as user safety signals.



Details on speed monitoring

- -When the door is open, the CNC and drive CPUs redundantly monitor if the command speed and FB speed exceed the safety speed or not
- -If it is detected that the safety speed is exceeded, emergency stop will be carried out to shut-down the Drive Unit's power
- -Individual selection is possible for each door whether to enable/disable monitoring (For up to 16 doors)





*Safety speed: Parameter setting available

Feed axis: 2,000mm/min or below,

spindle: 50r/min or below



